

**i.MX35 Modul phyCORE-i.MX35****Errata**

- Boot-Select-Problem
  - there are problems with the setting of the boot device with the current module versions up to PCB version 1315.3. The signals X\_BOOT3 and X\_BOOT4 are not connected correctly. Therefor a selection of the boot mode for booting out of NAND-Flash is not possible. This problem will be fixed with PCB version 1315.4.